



- ✓ Rapid action
- ✓ Keeps drains running freely



**Always Wear
Correct PPE
Check Safety
Data Sheet**

Hazardous Pictograms



1
Wear gloves. Pour entire contents down plughole, taking care to wipe up any spillages immediately.



2
Leave for at least 3 hours but preferably overnight



3
Flush thoroughly with hot water for at least 2 minutes until drain is running freely



4
It is essential that drains and surrounding areas (shower tray, sink, baths) are rinsed thoroughly before being used